	LOCATIONAL IDENTIFIER Service	LEAD GOOSENECK	CURRENT STREET SIDE	WAS STREET SIDE SERVICE LINE	STREET SIDE	STREET SIDE	CURRENT PROPERTY SIDE	PROPERTY	PROPERTY SIDE SERVICE LINE BUILDING OR POINT-OF-LINE	tY SF BUILDING		BUILDING PLUMBING		BASIS OF STREET SIDE	WAS STREE	SIDE FIELD STREET SIDE	BASIS OF PROPERTY	WAS PROPERTY	PROPERTY SIDE P	METHOD OF ROPERTY SIDE	NOTES ON BASIS OF
Owner Name	Address	CURRENTLY PRESENT?	SERVICE LINE MATERIAL	MATERIAL EVER PREVIOUSLY LEAD?	SERVICE S LINE SIZE II			LINE SIZE	INSTALL DATE  SERVICE LINE TYPE TYPE TREATMENT PRESENT?	PLUMBING MATERIAL 1	PLUMBING L MATERIAL 2	MATERIAL INSTALL DATE	COMMENTS	MATERIAL CLASSIFICATION	MATERIA FIELD VERIFIED	VERIFICATION, IF APPLICABLE  FIELD  VERIFICATION, II APPLICABLE		SIDE MATERIAL FIELD VERIFIED?	FIELD VERIFICATION, IF VE APPLICABLE	FIELD ERIFICATION, IF APPLICABLE	MATERIAL CLASSIFICATION
	0 BALL FIELDS FOOTE AVENUE	N UNK	DI UNK-LG	N LINK	6" 3/4"		DI :			0				Installed after lead ban Other - describe in notes	Y		Diameter > 2 inches Field inspection only	Y	Vis	ual insp at meter ual insp at mete	NO RECORD
	100 E STOCKMAN STREET	N N	C C	N N	1"		C :			0				SL repair/replace record	N N		Other - describe in note:	Y		ual insp at meter	NO RECORD
	1000 S WESTLAND 1000 W SILVER FOX DRIVE	N N	P	N N	1 1/2"	1992	P :	1/2"	2023	0				Installed after lead ban Installed after lead ban	Y	Visual insp during install	Installed after lead ban Installed after lead ban	Y		during install or re ual insp at meter	epair
	1002 W RED FOX RUN	N	C	N	1"	1552	P :		2021	0				Installed after lead ban	N		Installed after lead ban	Ý	Vis	ual insp at meter	
	1005 W CARDINAL DRIVE 1012 W RED FOX RUN	N N	C	N N	1"		P :	1/2"	2021	C				Installed after lead ban Installed after lead ban	N N		Installed after lead ban Installed after lead ban	Y		ual insp at meter ual insp at meter	
	1015 W CARDINAL DRIVE	N	c	N	1"		P		1011	0				Installed after lead ban	N		Installed after lead ban	Ϋ́	Vis	ual insp at meter	
	1020 W CARDINAL DRIVE 1020 W RED FOX RUN	N N	C	N N	1"		C :			C				Installed after lead ban Installed after lead ban	N N		Installed after lead ban Installed after lead ban	Y		ual insp at meter ual insp at meter	
	1025 W CARDINAL DRIVE	N	c	N	1"		c :			c				Installed after lead ban	N		Installed after lead ban	Ÿ	Vis	ual insp at meter	
	103 E STATE ROAD 29 103 S UPPER GLADE AVENUE	UNK	C UNK-LG	N UNK	3/4"			/4" /4"		0				Installed after lead ban Other - describe in notes	N N		Installed after lead ban Other - describe in note:	Y		ual insp at meter ual insp at mete	NO RECORD
	1030 W SILVER FOX DRIVE	N	С	N	1"		P :			0				Installed after lead ban	N		Installed after lead ban	Ÿ	Vis	ual insp at meter	
	1031 W SILVER FOX DRIVE 1035 W CARDINAL DRIVE	N N	C	N N	1"			1/2"		0				Installed after lead ban Installed after lead ban	N N		Installed after lead ban Installed after lead ban	Y		ual insp at meter ual insp at meter	
	104 S SABIN AVENUE	N N	С	N	3/4"		c :	/4"		0				Installed after lead ban	N		Installation record	Y	Vis	ual insp at meter	
	1040 W CARDINAL DRIVE 1045 W CARDINAL DRIVE	N	C	N N	1"		P :	•		0				Installed after lead ban Installed after lead ban	N N		Installed after lead ban Installed after lead ban	Y	Vis	ual insp at meter ual insp at meter	
	1049 W RED FOX RUN 105 N MCKAY AVENUE	N N	c	N	1" 3/4"		c :	/4"		c				Installed after lead ban SL repair/replace record	N		Installed after lead ban	Y	Vis	ual insp at meter	
	105 S MCKAY AVENUE	N N	C	N N	3/4"			-		0				SL repair/replace record	N N		Installed after lead ban	Y		ual insp at meter ual insp at meter	
	105 S NEWMAN AVENUE 105 S SABIN AVENUE	N Y	С	N N	2"		c :			С				Installed after lead ban	N		Installed after lead ban	Y		ual insp at meter	
	105 W STATE STREET	N	C	N N	3/4" 1"		C :	/4" /4"		C				Installed after lead ban Installed after lead ban	Y		Installed after lead ban Installed after lead ban	Y		ual insp at meter ual insp at meter	
	1050 S WASON DR 1050 W RED FOX RUN	N N	С	N N	1"			1/2"	2022	0				Installed after lead ban Installed after lead ban	Y	Visual insp during install	Installed after lead ban Installed after lead ban	Y		during install or re ual insp at meter	epair
	1051 W RED FOX RUN	N	c	N	1"			1/2"		0				Installed after lead ban	N N		Installed after lead ban	Y		ual insp at meter	
	1055 W CARDINAL DRIVE 106 N MCKAY AVENUE	N N	C	N N	1" 3/4"		C :	1/2"		0				Installed after lead ban SL repair/replace record	N		Installed after lead ban Installed after lead ban	Y	Vis	ual insp at meter ual insp at meter	
	106 W IRON STREET	UNK	UNK-LG	UNK	3/4"		C :	/4"		C				Other - describe in notes	N		Installed after lead ban	Y	Vis	ual insp at mete	NO RECORD
	106 W NORTH 2ND STREET 1060 S WASSON DR	N N	C	N N	3/4"		C :	/4"	2023	C				Installed after lead ban Installed after lead ban	N	Visual insp during install	Field inspection only	Y		ual insp at meter during install or re	ensir
	1065 W CARDINAL DRIVE	N	C	N	1"				1013	C				Installed after lead ban	N	Visual hisp during histori	Installed after lead ban	Y	Vis	ual insp at meter	.pun
	107 N NEWMAN AVENUE 107 N SABIN AVENUE	N N	C	N N	3/4"			/4" /4"		C				Installed after lead ban Installed after lead ban	N N		Installed after lead ban Field inspection only	Y	Vis	ual insp at meter ual insp at meter	
	107 S MCKAY AVENUE	N	C	N	3/4"		C :	/4"		C				SL repair/replace record	N		Installed after lead ban	Ý	Vis	ual insp at meter	
	1070 S WESTLAND DRIVE 1075 S WASSON DRIVE	N N	C DI	N N	1" 8"			1/2" inch		0				Installed after lead ban Installed after lead ban	N N		Installed after lead ban Installed after lead ban	Y		ual insp at meter ual insp at meter	
	1075 S WESTLAND DRIVE	N	DI	N	8"		c :			C				Installed after lead ban	N		Installed after lead ban	Y	Vis	ual insp at meter	
	1075 W CARDINAL DRIVE 1079 W RED FOX RUN	N N	C	N N	1"		P :	1/2"		C				Installed after lead ban Installed after lead ban	N N		Installed after lead ban Installed after lead ban	Y		ual insp at meter ual insp at meter	
	108 N SABIN AVENUE	N	C	N	3/4"			/4"		0				Installed after lead ban	N		Field inspection only	Ý	Vis	ual insp at meter	
	108 S MCKAY AVENUE 1080 W RED FOX RUN	N N	C	N N	3/4" 1"		C :			C				Installed after lead ban Installed after lead ban	N N		Installed after lead ban Installed after lead ban	Y	Vis Vis	ual insp at meter ual insp at meter	
	1085 W CARDINAL DRIVE	N	c	N	1"			1/2"		C				Installed after lead ban	N		Installed after lead ban	Y	Vis	ual insp at meter	
	109 W CENTRAL STREET 1090 W SILVER FOX DRIVE	N N	C	N N	3/4"		C :	/4"		C				SL repair/replace record Installed after lead ban	N N		Installed after lead ban Installed after lead ban	Y		ual insp at meter ual insp at meter	
	1091 W SILVER FOX DRIVE	N N	C	N	1"		C :	•		C				Installed after lead ban	N		Installed after lead ban	Y	Vis	ual insp at meter	
	1095 S WESTLAND DRIVE 1095 W CARDINAL DRIVE	N N	C	N N	1"		P :			0				Installed after lead ban Installed after lead ban	N N		Installed after lead ban Installed after lead ban	Y		ual insp at meter ual insp at meter	
	110 E CLEVELAND STREET	N N	С	N	3/4"			/4"		С				SL repair/replace record	Y		Installed after lead ban	Y		ual insp at meter	
	1100 W WHITETAIL RUN 1101 W WHITETAIL RUN	N N	C	N N	1"		C :			C				Installed after lead ban Installed after lead ban	N N		Installed after lead ban Installed after lead ban	Y	Vis Vis	ual insp at meter ual insp at meter	
	1102 W ASPEN DRIVE	N N	С	N	1"		c :	1/2"		0				Installed after lead ban	N		Installed after lead ban	Y	Vis	ual insp at meter	
	1103 W ASPEN DRIVE 1105 W BELTLINE ROAD	N	C	N N	1"		C :	/4"		C				Installed after lead ban Installed after lead ban	N N		Installed after lead ban Installed after lead ban	Y		ual insp at meter ual insp at meter	
	1105 W CARDINAL DRIVE	N	C	N	1"					0				Installed after lead ban	N		Installed after lead ban	Y		ual insp at meter	
	1105 W WHITETAIL RUN 111 E CENTRAL STREET	N N	C	N N	1"		C :	/4"		C				Installed after lead ban Installed after lead ban	Y	2021	Installed after lead ban Installed after lead ban	Y		ual insp at meter ual insp at meter	
	111 E STOCKMAN STREET 111 N SABIN AVENUE	N N	C	N .	1" 3/4"			/4" /2"		C				Installed after lead ban Installed after lead ban	N		Installed after lead ban Installed after lead ban	Y	Vis	ual insp at meter ual insp at meter	
	111 S MCKAY AVENUE	N	C	N N	3/4"		C :	/4"		C				SL repair/replace record	N N		Installed after lead ban	Y	Vis	ual insp at meter	
	111 S SABIN AVENUE 1110 W WHITETAIL RUN	N N	c	N N	3/4"		C :	/4"		C				Installed after lead ban Installed after lead ban	N		Installed after lead ban Installed after lead ban	Y	Vis	ual insp at meter ual insp at meter	
	1111 W WHITETAIL RUN	N	c	N N	1"		c :			C				Installed after lead ban	N		Installed after lead ban	Y	Vis	ual insp at meter	
	1112 W ASPEN DRIVE 1113 W ASPEN DRIVE	N N	C	N .	1"		C :			C				Installed after lead ban Installed after lead ban	N		Installed after lead ban Installed after lead ban	Y		ual insp at meter ual insp at meter	
	1115 W CARDINAL DRIVE	N	C	N N	1"		P :			C				Installed after lead ban	N		Installed after lead ban	Ý	Vis	ual insp at meter	
	1115 W WHITETAIL RUN 112 N MCKAY AVENUE	N N	C	N	1"		C :	/4"		C				Installed after lead ban Installed after lead ban	N N		Installed after lead ban Installed after lead ban	Y		ual insp at meter ual insp at meter	
	112 W SOUTH 2ND STREET	N	c	N N	3/4"			1/2"		0				Installed after lead ban	N		Installed after lead ban	Y	Vis	ual insp at meter	
	1121 W WHITETAIL RUN 1122 W ASPEN DRIVE	N N	C	N N	1"		c :			C				Installed after lead ban Installed after lead ban	N N		Installed after lead ban Installed after lead ban	Y	Vis Vic	ual insp at meter ual insp at meter	
	113 N NEWMAN AVENUE	N	č	N	3/4"			/4"		C				Installed after lead ban	N		Installed after lead ban	Y	Vis	ual insp at meter	
	113 S MCKAY AVENUE 1130 W WHITETAIL RUN	N N	C	N N	3/4" 1"		C :			C				Installed after lead ban Installed after lead ban	N N		Installed after lead ban Other - describe in note:	Y	Vis	ual insp at meter ual insp at meter	
	1131 W WHITETAIL RUN	N	c	N	1"			/4"		С				Installed after lead ban	N		Installed after lead ban	Y	Vis	ual insp at meter	
	1132 W ASPEN DRIVE 1133 W ASPEN DRIVE	N N	C	N N	1"		C :			C				Installed after lead ban Installed after lead ban	N N		Installed after lead ban Installed after lead ban	Y		ual insp at meter ual insp at meter	
	1133 W WHITETAIL RUN	N N	c	N	1"		c :	-		C				Installed after lead ban	N		Installed after lead ban	Y	Vis	ual insp at meter	
	1137 W BELTLINE ROAD 114 E AKERS STREET	N N	C	N N	3/4"		C	/4" /4"		C				Installed after lead ban SL repair/replace record	N Y	2022 nsp during install	Installed after lead ban Field inspection only	Y		ual insp at meter ual insp at meter	
	114 W FIRST STREET	N N	C	N	3/4"		c :			С				SL repair/replace record	N		Field inspection only	Y	Vis	ual insp at meter	
	1140 W WHITETAIL RUN 1141 W BELTLINE ROAD	N N	C	N N	1"		C :			C				Installed after lead ban Installed after lead ban	N N		Installed after lead ban Installed after lead ban	Y	Vis	ual insp at meter ual insp at meter	
	1142 W ASPEN DRIVE	N N	C	N P	1"		c :			c				Installed after lead ban	N		Installed after lead ban	Y	Vis	ual insp at meter	
	1143 W WHITETAIL RUN 1149 W MARYANN ST	N	C	N N	1"	2024	P		2024	0				Installed after lead ban Installed after lead ban	Y	Visual insp during install	Installed after lead ban Installed after lead ban	Y	Visual insp	ual insp at meter during install or re	epair
	115 N SABIN AVENUE	N N	c	N	3/4"			/4"		0				Installed after lead ban	N		Field inspection only	Y	Vis	ual insp at meter	
	115 S SABIN AVENUE 115 W NORTH FOURTH STREET	N	C	N N	3/4"			/4" /4"		C				Installed after lead ban SL repair/replace record	N N		Field inspection only Field inspection only	Y		ual insp at meter ual insp at meter	
	115 W STATE STREET	N N	c	N	1"		C :			C				Installed after lead ban	N		Field inspection only	Y	Vis	ual insp at meter	
	1150 W WHITETAIL RUN 1152 W ASPEN DRIVE	N	C	N N	1"		C :			0				Installed after lead ban Installed after lead ban	N N		Installed after lead ban Installed after lead ban	Y	Vis	ual insp at meter ual insp at meter	
	1153 W MARYANN ST	N	C	N	1"	2024	P :	/4"	2024	0				Installed after lead ban	Y	Visual insp during install	Installed after lead ban	Y	Visual insp	during install or re	epair
	1153 W WHITETAIL RUN 1157 W MARYANN STREET	N N	C C	N N	1"		C :			C				Installed after lead ban Installed after lead ban	N N		Installed after lead ban Installed after lead ban	Y		ual insp at meter ual insp at meter	
	116 E NORTH FOURTH STREET	N N	C	N	1"		c :	/4"		0				Installed after lead ban	N		Field inspection only	Y	Vis	ual insp at meter	
	116 S MCKAY AVENUE 1161 S HIGHLAND SPRINGS	N	C	N N	3/4" 1"		C :			0				SL repair/replace record Installed after lead ban	N N		Field inspection only Installed after lead ban	Y	Vis Vis	ual insp at meter ual insp at meter	
	1161 W MARYANN STREET	N	C	N	1"		C :			C				Installed after lead ban	N		Installed after lead ban	Y	Vis	ual insp at meter	
	1162 W ASPEN DRIVE	N	С	N	1"		C :	•		C				Installed after lead ban	N		Installed after lead ban	Y	Vis	ual insp at meter	

1163 S HIGHLAND SPRINGS 1163 W WHITETAIL RUN	N C	N N	1"		C 1	1"		C	Installed after lead ban Installed after lead ban	N Installed after lead ban N Installed after lead ban	Y Visual insp at meter Y Visual insp at meter
1165 S HIGHLAND SPRINGS	N C	N N	1"			3/4"		c	Installed after lead ban	N Installed after lead ban	Y Visual insp at meter
1165 W MARYANN STREET	N C	. N	1"		C 1	l"		C	Installed after lead ban	N Installed after lead ban	Y Visual insp at meter
1167 S HIGHLAND SPRINGS	N C	. N	1"		C 1	i"		C	Installed after lead ban	N Installed after lead ban	Y Visual insp at meter
1169 S HIGHLAND SPRINGS	N C	. N	1"		C 1	1"		С	Installed after lead ban	N Installed after lead ban	Y Visual insp at meter
1169 W MARYANN STREET	N C	. N	1"			1 1/2"		C	Installed after lead ban	N Installed after lead ban	Y Visual insp at meter
117 W IRON STREET	UNK UNK-	-LG UNI	K 3/4"		C 3	3/4"		C	Other - describe in notes	N Field inspection only	Y Visual insp at mete NO RECORD
1171 S HIGHLAND SPRINGS	N C	: N	1"		C 1	i"		C	Installed after lead ban	N Installed after lead ban	Y Visual insp at meter
1173 W MARYANN STREET	N C	. N	1"		C 1	i"		C	Installed after lead ban	N Installed after lead ban	Y Visual insp at meter
1177 W MARYANN STREET 118 W NORTH 2ND STREET	UNK UNK-	LG UNI	IK 3/4"			3/4"		C	Installed after lead ban Other - describe in notes	N Installed after lead ban N Field inspection only	Y Visual insp at meter Y Visual insp at mete NO RECORD
118 W NORTH 2ND STREET 1182 W OAK RIDGE COURT	N C	-LG UNI	1"			1/4"		c	Installed after lead ban	N Installed after lead ban	Y Visual insplat meter NO RECORD
1186 S COTTAGE LANE	N C	. N	1"			1 1/2"		C	Installed after lead ban	N Installed after lead ban	Y Visual insp at meter
1187 S COTTAGE LANE	N C	. N	1"			1 1/2"		C	Installed after lead ban	N Installed after lead ban	Y Visual insp at meter
119 E CENTRAL STREET	N C	. N	2"		C 2	)"		0	SL repair/replace record	Y Field inspection only	Y Visual insp at meter
119 S MCKAY AVENUE	N C	N	3/4"		C 3	3/4"		0	SL repair/replace record	N Field inspection only	Y Visual insp at meter
119 W STATE STREET	N C	: N	1"		Unknown 3	3/4"		0	Installed after lead ban	N Field inspection only	Y Visual insp at meter
1192 W OAK RIDGE COURT	N C	. N	1"		C 1	i"		С	Installed after lead ban	N Installed after lead ban	Y Visual insp at meter
120 N MCKAY AVENUE	N C	. N	3/4"		C 1	i"		C	SL repair/replace record	N Field inspection only	Y Visual insp at meter
1202 W OAK RIDGE CT	N C	. N	1"		P 1	ı"	2021	0	Installed after lead ban	Y Visual insp during install o Installed after lead ban	Y Visual insp during install or repair
1203 W BELTLINE ROAD	N C	. N	1"		C 1	l"		C	Installed after lead ban	N Installed after lead ban	Y Visual insp at meter
1204 W MARYANN STREET	N C	. N	1"		C 1	i"			Installed after lead ban	N Installed after lead ban	Y Visual insp at meter
121 E SOUTH 2ND STREET	N C	. N	1"		C 1	ı"		С	Installed after lead ban	N Installed after lead ban	Y Visual insp at meter
121 N NEWMAN AVENUE 121 N SABIN AVENUE	N C	. N	3/4"	2014	C 3	3/4"		0	SL repair/replace record Installed after lead ban	N Field inspection only N Field inspection only	Y Visual insp at meter Y Visual insp at meter
121 N SABIN AVENUE 121 W AKERS STREET	N C	. N	3/4"	2014	C 1	3/4"		0			
121 W FIRST STREET	N C	. N	3/4"			3/4			Installed after lead ban	N Installed after lead ban	Y Visual insp at meter
121 W FIRST STREET  121 W SOUTH 2ND STREET	N C	. N	3/4"		6 1	3/4"		U	C pipe @curbstop SL repair/replace record Installed after lead ban	N 2023 nsp during install o Field inspection only N Installed after lead ban	Y Visual insp at mete COPPER @CURB ST Y Visual insp at meter
121 W LOIS STREET	N C	. N	3/4		0 1	3/4		0	Installed after lead ban	N Installed after lead ban	Y Visual insp at meter  Y Visual insp at meter
121-123-125 S MCKAY AVENUE	N C	. N	3/4"			3/4"		c	SL repair/replace record	N Installed after lead ban	Y Visual insp at meter
1212 W LOIS STREET	N C	. N	1"		P 1			0	Installed after lead ban	N Installed after lead ban	Y Visual insp at meter
1212 W MARYANN STREET	N C	. N	1"		C 1	ı"		С	Installed after lead ban	N Installed after lead ban	Y Visual insp at meter
1216 W MARYANN STREET	N C	. N	1"		P 1	i"		С	Installed after lead ban	N Installed after lead ban	Y Visual insp at meter
1217 W BELTLINE ROAD	N C	: N	1"		C 1	i"		С	Installed after lead ban	N Installed after lead ban	Y Visual insp at meter
1217 W LOIS STREET	N C	. N	1"		С 3	3/4"		С	Installed after lead ban	N Installed after lead ban	Y Visual insp at meter
1218 W LOIS STREET	N C	. N	1"		P 1	i"		0	Installed after lead ban	N Installed after lead ban	Y Visual insp at meter
122 S GLADE AVENUE	UNK UNK-	-LG UNI			UNK-LG				Other - describe in notes	N Other - describe in note:	Y Visual insp at mete NO RECORD
122 W FIRST STREET	N C	. N	3/4"		C 3	3/4"		C	Installed after lead ban	N Field inspection only	Y Visual insp at meter
122 W IRON STREET	N C	. N	2"		C 2	2"		С	Diameter > 2 inches	N Field inspection only	Y Visual insp at meter
122 W IRON STREET 122 W NORTH FOURTH STREET	N C	N N	2*		C 2			C	Diameter > 2 inches	N Field inspection only	Y Visual insp at meter
122 W NORTH FOURTH STREET	N C	. N	3/4"		C 3	3/4"		U	SL repair/replace record	N Field inspection only	Y Visual insp at meter
1220 S COTTAGE LANE 1221 S COTTAGE LANE	N C	. N	1"		C 1	1 1/2"		c	Installed after lead ban Installed after lead ban	N Field inspection only N Field inspection only	Y Visual insp at meter Y Visual insp at meter
	N C	. N	1"		C 1	1 1/2"		C			
1221 W BELTLINE ROAD 1223 W LOIS STREET	N C	. N	1"		C 1	1"		C	Installed after lead ban Installed after lead ban	N Field inspection only N Field inspection only	Y Visual insp at meter
	N C	. N	1"		P 1			c		N Field inspection only	Y Visual insp at meter Y Visual insp at meter
1224 W LOIS STREET 1224 W MARYANN STREET	N C	. N	1"		C 1			0	Installed after lead ban Installed after lead ban	N Field inspection only N Field inspection only	Y Visual insp at meter  Y Visual insp at meter
1229 W BELTLINE ROAD	N C	N N	1"		C 1			c	Installed after lead ban	N Field inspection only	Y Visual insp at meter
1229 W LOIS STREET	N C	. N	1"		P 1			C	Installed after lead ban	N Field inspection only	Y Visual insp at meter
1229 W MARYANN STREET	N C	. N	1"		C 1			C	Installed after lead ban	N Field inspection only	Y Visual insp at meter
123 E STOCKMAN STREET	N C	. N	3/4"			3/4"		c	SL repair/replace record	N Field inspection only	Y Visual insp at meter
123 S UPPER GLADE AVENUE	UNK UNK-	-LG UNI				3/4"		0	Other - describe in notes	N Field inspection only	Y Visual insp at mete NO RECORD
123 W IRON STREET	UNK UNK-					3/4"		c	Other - describe in notes	N Field inspection only	Y Visual insp at mete NO RECORD
124 E AKERS STREET	N C	. N	3/4"			3/4"		c	SL repair/replace record	N Field inspection only	Y Visual insp at meter
124 S NEWMAN AVENUE	N C	. N	3/4"		C 3	3/4"		С	Installed after lead ban	N Field inspection only	Y Visual insp at meter
124 W SOUTH 2ND STREET	N C	. N	1"		C 3	3/4"		0	Installed after lead ban	N Field inspection only	Y Visual insp at meter
125 N MCKAY AVENUE	N C	. N	3/4"		G 3	3/4"		C	SL repair/replace record	N Field inspection only	Y Visual insp at meter
125 N SABIN AVENUE	N C	. N	3/4"	2014	P 1			C	Installed after lead ban	N Field inspection only	Y Visual insp at meter
125 S SABIN AVENUE	UNK UNK-	-LG UNI				3/4"		C	Other - describe in notes	N Field inspection only	Y Visual insp at mete NO RECORD
125 W STATE STREET	N C	. N	1"	2021	C 3	3/4"		С	Installed after lead ban	N Field inspection only	Y Visual insp at meter
126 N NEWMAN AVENUE	N C	. N	3/4"		G 1	ı"		0	Installed after lead ban	N Field inspection only	Y Visual insp at meter
126 N SABIN AVENUE	N C	. N	3/4"		C 3	3/4"		0	Installation record	N Field inspection only	Y Visual insp at meter
126 S MCKAY AVENUE	N C	. N	2"		C 2	2"		0	SL repair/replace record	N Field inspection only	Y Visual insp at meter
127 S MCKAY AVENUE 130 S GLADE AVENUE	N C	. N	3/4"		C 3	3/4"		C	SL repair/replace record Installation record	N Field inspection only N Field inspection only	Y Visual insp at meter Y Visual insp at meter
130 S GLADE AVENUE	N C	. N	3/4"		C 2	3/4"		0			Y Visual insplat meter Y Visual insplat meter
1303 W SKYLINE DRIVE	N C	. N	3/4		C 1	1"		C	SL repair/replace record Installed after lead ban	N Field inspection only N Field inspection only	Y Visual insp at meter  Y Visual insp at meter
1306 W SKYLINE DRIVE	N C	. N	1"		C 1			C	Installed after lead ban	N Field inspection only	Y Visual insp at meter
131 N MCKAY AVENUE	N C	. N	3/4"			3/4"		c	SL repair/replace record	N Field inspection only	Y Visual insp at meter
131 N NEWMAN AVENUE	N C	N N	3/4"			3/4"		c	St repair/replace record Installation record	Field inspection only	Y Visual insp at meter Y Visual insp at meter
131 S MCKAY AVENUE	N C	. N	3/4"			3/4"		c	SL repair/replace record	N Field inspection only	Y Visual insp at meter
131 S MCKAY AVENUE	N C	. N	3/4"			3/4"		С	SL repair/replace record	N Field inspection only	Y Visual insp at meter
1312 W SKYLINE DRIVE	N C	. N	1"	i i	C 1			C	Installed after lead ban	N Field inspection only	Y Visual insp at meter
1315 W SKYLINE DRIVE	N C	. N	1"		C 1	i"		C	Installed after lead ban	N Field inspection only	Y Visual insp at meter
132 N MCKAY AVENUE	N C	N N	3/4"			3/4"		c	SL repair/replace record	N Field inspection only	Y Visual insp at meter
132 N NEWMAN AVENUE	N C	. N	3/4"			3/4"		0	Installation record	N Field inspection only	Y Visual insp at meter
133 N SABIN AVENUE	N C	. N	3/4"		C 3	3/4"		C	Installation record	N Field inspection only	Y Visual insp at meter
133 S UPPER GLADE AVENUE	UNK UNK-	-LG UNI	IK		C 1	i"		C	Other - describe in notes	Field inspection only	Y Visual insp at mete NO RECORD
134 S GOLFVIEW DRIVE	N C	. N	1"		C 1			c	Installation record	N Field inspection only	Y Visual insp at meter
1345 W SKYLINE DRIVE 135 N NEWMAN AVENUE	N C	N	1" 3/4"		C 1	3/4"		C	Installed after lead ban	N Field inspection only	Y Visual insp at meter
	N C	. N						0		N Field inspection only	Y Visual insp at meter
136 N MCKAY AVENUE 136 S MCKAY AVENUE	N C	. N	3/4"			3/4"		0	SL repair/replace record	N Field inspection only	Y Visual insp at meter
136 S MCKAY AVENUE 137 E STOCKMAN STREET	N C	. N	3/4"			3/4" 3/4"	1	C	SL repair/replace record	N Field inspection only N Field inspection only	Y Visual insp at meter
137 E STOCKMAN STREET 1375 W SKYLINE DRIVE	N C	N N	3/4"		D 4	·/→		C	SL repair/replace record Installed after lead ban	N Field inspection only N Field inspection only	Y Visual insp at meter Y Visual insp at meter
1375 W SKYLINE DRIVE 139 N MCKAY AVENUE	N C	. N	3/4"		. 1	3/4"		C	SL repair/replace record	N Field inspection only N Field inspection only	Y Visual insp at meter Y Visual insp at meter
140 N MCKAY AVENUE	N C	N	3/4"			3/4"		0	St repair/replace record St repair/replace record	N Field inspection only	Y Visual insp at meter Y Visual insp at meter
140 N NEWMAN AVENUE	N C	. N	3/4"			3/4"		c	Installation record	N Field inspection only	Y Visual insp at meter
140 S MCKAY AVENUE	N C	N	3/4"			3/4"		C	SL repair/replace record	N Field inspection only	Y Visual insp at meter
1401 W SKYLINE DRIVE	N C	. N	1"		C 1	ı"		С	Installed after lead ban	N Field inspection only	Y Visual insp at meter
141 N SABIN AVENUE	N C	. N	3/4"		С 3	3/4"		0	Installation record	N Field inspection only	Y Visual insp at meter
141 S GOLFVIEW DRIVE	N C	N N	1"		C 3	3/4"		С	Installed after lead ban	Field inspection only	Y Visual insp at meter
1412 W SKYLINE DRIVE	N C	. N	1"		C 1	i"		С	Installed after lead ban	N Field inspection only	Y Visual insp at meter
1418 W SKYLINE DRIVE	N C	. N	1"		G 1	1/2"		С	Installed after lead ban	N Field inspection only	Y Visual insp at meter
142 N SABIN AVENUE	N C	. N	3/4"		С 3	3/4"		C	Installation record	Field inspection only	Y Visual insp at meter
1422 W WESTVIEW COURT	N C	. N	1"		C 1	i"		C	Installed after lead ban	N Field inspection only	Y Visual insp at meter
1425 W WESTVIEW COURT	N C	. N	1"		С 3	3/4"		c	Installed after lead ban	N Field inspection only	Y Visual insp at meter
1428 W SKYLINE DRIVE	N C	. N	1"		C 1	i"		С	Installed after lead ban	N Field inspection only	Y Visual insp at meter
	UNK UNK-	-LG UNI				3/4"		0	Other - describe in notes	Field inspection only	Y Visual insp at mete NO RECORD
143 S UPPER GLADE AVENUE	N C	. N	1"		C 1	1"		С	Installed after lead ban	N Field inspection only	Y Visual insp at meter
143 S UPPER GLADE AVENUE 1430 W SKYLINE DRIVE	N DI	I N	6"		C 4	1"		c	Diameter > 2 inches	N Field inspection only	Y Visual insp at meter
143 S UPPER GLADE AVENUE 1430 W SKYLINE DRIVE 1450 S CTY TRUNK HWY CC	N DI	I N	8"		C 4	1"		C	Diameter > 2 inches	N Field inspection only	Y Visual insp at meter
143 S UPPER GLADE AVENUE 1430 W SKYLINE DRIVE 1450 S CTY TRUNK HWY CC 1450 S CTY TRUNK HWY CC	i Di	. N	1"		C 3	3/4"		С	Installed after lead ban	N Field inspection only	Y Visual insp at meter
143 S UPPER GLADE AVENUE 1430 W SKYLINE DRIVE 1450 S CTY TRUNK HWY CC 1450 S CTY TRUNK HWY CC 1450 W SKYLINE DRIVE 1450 W SKYLINE DRIVE	N C				C 1	l"		C	Installed after lead ban	N Field inspection only	Y Visual insp at meter
143 S UPPER CLOE AVENUE  1490 W SEVILADE DRIVE  1450 S CTY TRUNK HWY CC  1450 W SKYLINE DRIVE  1640 W MEADOW LANE	N C	. N	1"								
143 UPPER GLADE AVENUE \$430 W SCYLINE DRIVE 1450 S CTY TRUNK HWY CC 1450 S CTY TRUNK HWY CC 1450 W SCYLINE DRIVE 1450 W WEADOW LANE 1656 W MEADOW LANE	N C N C	N N	1" 1"		C 1	i"		C	Installed after lead ban	N Field inspection only	Y Visual insp at meter
143 UPPER CLADE AMPHUE 1400 W SCYLINE BRIVE 1405 SCYT TRUNK HWY CC 1405 SCYT TRUNK HWY CC 1405 W SCYLINE BRIVE 1606 W MEADOW LANE 1606 W MEADOW LANE 1606 W MEADOW LANE	N C	N N	1" 1" 1"		C 1	i.		C O	Installed after lead ban Installed after lead ban		Y Visual insp at meter Y Visual insp at meter
143 UPPER CALDE AVENUE 1430 W STRIME BRIVE 1400 W STRIME BRIVE 1400 SCT TRUNK HMY CC 1400 W STRIME DRIVE 1400 W STRIME DRIVE 1500 W STRIME DRIVE 1500 W MEADOW LANE 1500 W MEADOW LANE 1500 W MEADOW LANE	N C N C N C N C N C N C	N N N	1" 1" 1"	1	C 1 C 1 C 1			0 0	Installed after lead ban Installed after lead ban Installed after lead ban	N         Field inspection only           N         Field inspection only           N         Field inspection only	Y Visual insp at meter Y Visual insp at meter Y Visual insp at meter
143 S UPPER GLODE AVENUE 14390 SCYNINE BRIVE 1459 S CYT TRUNK HWY CC 14590 W SCYLINE BRIVE 1458 CST TRUNK HWY CC 14590 W SCYLINE BRIVE 1566 W MEADOW LANE 1566 W MEADOW LANE 1666 W MEADOW LANE	N C N C	N N N	1" 1" 1" 1"					0 0 0	Installed after lead ban Installed after lead ban	N Field inspection only N Field inspection only	Y Visual insp at meter Y Visual insp at meter

1674 W MEADOW LANE	N	С	N	1"	C 3/4"			0	Installed after lead ban	N	Field inspection only	Y Visual insp at meter	f
1676 W MEADOW LANE	N	С	N	1"	C 3/4"			0	Installed after lead ban	N	Field inspection only	Y Visual insp at meter	r
1678 W MEADOW LANE	N N	c	N	1"	C 1"			0	Installed after lead ban	N	Field inspection only Field inspection only	Y Visual insp at meter Y Visual insp at meter	
180 S GOLFVIEW DRIVE	N	C	N N	1"	C 3/4"			C	Installed after lead ban	N N	Field inspection only	Y Visual insp at meter Y Visual insp at meter	
200 S GLADE AVENUE	UNK	UNK-LG	UNK	•	C 3/4"				Other - describe in notes	N	Field inspection only	Y Visual insp at mete	
200 S SABIN	N	С	N 1	1/2"	P 1 1/4	1"	2023	0	Installed after lead ban	Y Vis	ual insp during install o Installed after lead ban	Y Visual insp during install or	r repair
204 S GOLFVIEW DRIVE	N	С	N	1"	C 3/4"			C	Installation record	N	Field inspection only	Y Visual insp at meter	r
204 S MCKAY AVENUE 205 N NEWMAN AVENUE	N N	C		/4" /4"	C 3/4" G 3/4"			C	SL repair/replace record Installation record	N N	Field inspection only Field inspection only	Y Visual insp at meter Y Visual insp at meter	
205 N NEWMAN AVENUE	N	C		/4" 1995	C 3/4"			0	Installation record	N N	Field inspection only	Y Visual insp at meter Y Visual insp at meter	
206 W NORTH FOURTH STREET	N	C		/4" 1992	C 3/4"			C	SL repair/replace record	N	Field inspection only	Y Visual insp at meter	
207 N SABIN AVENUE	N	С		/4" 1995	C 3/4"			С	Installation record	N	Field inspection only	Y Visual insp at meter	r
207 S MCKAY AVENUE 207 W NORTH FOURTH STREET	N N	c	N 3	/4" /4"	C 3/4"				SL repair/replace record	N .	Field inspection only	Y Visual insp at meter	r
209 N MCKAY AVENUE	N	C	N 3	/4"	C 3/4"			C	SL repair/replace record SL repair/replace record	N N	Field inspection only Field inspection only	Y Visual insp at meter Y Visual insp at meter	,
209 S GOLFVIEW DRIVE	N	c		/4"	C 3/4"			C	Installation record	N	Field inspection only	Y Visual insp at meter	
209 S UPPER GLADE AVENUE	UNK	UNK-LG	UNK		C 3/4"			C	Other - describe in notes	N	Field inspection only	Y Visual insp at mete	NO RECORD
210 N MCKAY AVENUE	N	С		/4"	C 1"			C	Installation record	N	Field inspection only	Y Visual insp at meter	r
210 N SABIN AVENUE 210 W CLEVELAND STREET	UNK	C UNK-LG	N 3	/4"	C 3/4"			0	Installation record Other - describe in notes	N N	Field inspection only Field inspection only	Y Visual insp at meter Y Visual insp at meter	NO RECORD
211 N NEWMAN AVENUE	N	UNK-LG	N N	1"	C 3/4"			C	Installed after lead ban	N N	Field inspection only	Y Visual insp at meter Y Visual insp at meter	NO RECORD
211 S MCKAY AVENUE	N	c	N 3	/4"	C 1"			C	SL repair/replace record	N	Field inspection only	Y Visual insp at meter	r
212 N HERB AVENUE	N	С	N	1"	C 3/4"			0	SL repair/replace record	N	Field inspection only	Y Visual insp at meter	r
212 S MCKAY AVENUE	N	С		/4"	C 3/4"			UNK	SL repair/replace record	N	Field inspection only	Y Visual insp at meter	r
213 N SABIN AVENUE 213 W TERRACE STREET	N N	C		/4" /4"	C 3/4"			0	Installed after lead ban SL repair/replace record	N 2022	rield inspection only nsp during install o Field inspection only	Y Visual insp at meter Y Visual insp at meter	
214 S MCKAY AVENUE	N N	C		/4"	C 3/4"			C	SL repair/replace record	N 2023	Field inspection only	Y Visual insp at meter	,
214 W SOUTH THIRD STREET	N	c		/4"	C 3/4"			C	Installed after lead ban	N	Field inspection only	Y Visual insp at meter	r
215 S MCKAY AVENUE	N	С	N 3	/4"	C 5/8"			C	SL repair/replace record	N	Field inspection only	Y Visual insp at meter	r
215 W CENTRAL STREET	N	С		/4"	P 3/4"			0	SL repair/replace record	N	Field inspection only	Y Visual insp at meter	
215 W CLEVELAND STREET 216 S GOLFVIEW DRIVE	N	C		/4" /4"	C 3/4"			C	SL repair/replace record Field inspection only	Y 2020 Y 2021	nsp during install o Field inspection only nsp during install o Field inspection only	Y Visual insp at meter Y Visual insp at meter	
216 S MCKAY AVENUE	N	C		/4"	C 3/4"				SL repair/replace record	N 2021	Field inspection only	Y Visual insp at meter Y Visual insp at meter	r
217 N HERB AVENUE	N	С		1"	C 3/4"			0	SL repair/replace record	N	Field inspection only	Y Visual insp at meter	r
217 N MCKAY AVENUE	N	С	N 3	/4"	C 1"			0	Installation record	N	Field inspection only	Y Visual insp at meter	
217 N NEWMAN AVENUE	N	С	N	1"	C 3/4"			C	Installation record	N	Field inspection only	Y Visual insp at meter	
217 S MCKAY AVENUE 217 W NORTH 2ND STREET	N	C		/4" /4"	C 1/2"			C	SL repair/replace record Installation record	N N	Field inspection only Field inspection only	Y Visual insp at meter Y Visual insp at meter	
217 W NORTH 2ND STREET  217 W SOUTH THIRD STREET	N	C	N s	1"	C 1"			C	Installed after lead ban	N	Field inspection only	Y Visual insp at meter Y Visual insp at meter	r
217 W STATE ROAD 29	N	С	N	1" 2021	C 3/4"			С	Installed after lead ban	N	Field inspection only	Y Visual insp at meter	r
217-219 S GOLFVIEW DRIVE	N	C	N 3	/4"	C 3/4"			C	Installation record	N	Field inspection only	Y Visual insp at meter	r
218 N MCKAY AVENUE 218 S MCKAY AVENUE	N	С	N	1" /4"	C 1"			C	Installation record	N	Field inspection only	Y Visual insp at meter	r
218 W AKERS STREET	N N	C		/4"	C 3/4"			C	SL repair/replace record Installed after lead ban	N N	Field inspection only Field inspection only	Y Visual insp at meter Y Visual insp at meter	r
218 W CENTRAL STREET	N	c	N 3	/4"	C 3/4"			C	SL repair/replace record	N	Field inspection only	Y Visual insp at meter	1
218 W CLEVELAND STREET	UNK	UNK-LG	UNK		C 3/4"			0	Other - describe in notes	N	Field inspection only	Y Visual insp at mete	NO RECORD
218 W SOUTH THIRD STREET	N	С	N 3	/4"	C 3/4"			С	Installed after lead ban	N	Field inspection only	Y Visual insp at meter	r
219 W TERRACE STREET 220 N HERB AVENUE	UNK	UNK-LG	UNK		C 3/4"			C	Other - describe in notes	N	Field inspection only	Y Visual insp at mete	NO RECORD
220 N SABIN AVENUE	N N	C	N 2	1" /4"	C 3/4"			0	SL repair/replace record Installed after lead ban	N N	Field inspection only Field inspection only	Y Visual insp at meter Y Visual insp at meter	r
220 S GLADE AVENUE	UNK	UNK-LG	UNK	,-	C 3/4"			C	Other - describe in notes	N	Field inspection only	Y Visual insp at mete	NO RECORD
220 W STATE ROAD 29	N	С	N	1" 2021	G 3/4"			0	Installed after lead ban	Y	Field inspection only	Y Visual insp at meter	r
221 N MCKAY AVENUE	N N	С	N 3	/4"	C 3/4"			0	Installed after lead ban	N	Field inspection only	Y Visual insp at meter	r
221 N NEWMAN AVENUE 221 N SABIN AVENUE	N N	C	N .	1" /4"	P 1" C 3/4"			C	Installed after lead ban Installation record	N	Field inspection only Field inspection only	Y Visual insp at meter Y Visual insp at meter	
221 W CENTRAL STREET	N	C		/4"	C 3/4"			0	SL repair/replace record	N N	Field inspection only	Y Visual insp at meter Y Visual insp at meter	
222 W CENTRAL STREET	N	C		/4"	C 3/4"			C	SL repair/replace record	N	Field inspection only	Y Visual insp at meter	r
222 W CLEVELAND STREET	UNK	UNK-LG	UNK		C 3/4"			C	Other - describe in notes	N	Field inspection only	Y Visual insp at mete	NO RECORD
222 W TERRACE STREET	UNK	UNK-LG	UNK		C 3/4"			C	Other - describe in notes	N	Field inspection only	Y Visual insp at mete	NO RECORD
223 S MCKAY AVENUE 223 S NEWMAN AVENUE	N N	c		/4" /4"	C 3/4"			0	SL repair/replace record Installed after lead ban	N N	Field inspection only Field inspection only	Y Visual insp at meter Y Visual insp at meter	,
223 W FIRST STREET	N N	C	N s	1"	C 3/4"			C	Installation record	N N	Field inspection only	Y Visual insp at meter	
223 W SOUTH THIRD STREET	N	С	N 3	/4"	C 3/4"			С	Installation record	N	Field inspection only	Y Visual insp at meter	r
223 W STATE ROAD 29	N	C	N	1" 2021	C 3/4"			C	Installed after lead ban	N	Field inspection only	Y Visual insp at meter	r
224 N NEWMAN AVENUE	N N	С	N	1"	C 3/4"			C	Installation record	N	Field inspection only	Y Visual insp at meter	
224 S MCKAY AVENUE 224 W FIRST STREET	N N	C		/4" /4"	G 3/4" C 3/4"			C	SL repair/replace record SL repair/replace record	N N	Field inspection only Field inspection only	Y Visual insp at meter Y Visual insp at meter	,
225 N NEWMAN AVENUE	N	c		1"	C 1"			0	Installation record	N	Field inspection only	Y Visual insp at meter	
225 S MCKAY AVENUE	N	С	N 3	/4"	C 3/4"			0	SL repair/replace record	N	Field inspection only	Y Visual insp at meter	r
225 W CLEVELAND STREET	UNK	UNK-LG	UNK		G 11/4	1"		0	Other - describe in notes	N	Field inspection only	Y Visual insp at mete	NO RECORD
226 N HERB AVENUE	N UNK	C	N	1" /4"	C 3/4"			C	SL repair/replace record	N	Field inspection only	Y Visual insp at meter	NO RECORD
226 N MCKAY AVENUE	N N	UNK-LG		/4" /4"	C 3/4"			C	Installation record	N N	Field inspection only Field inspection only	Y Visual insp at meter Y Visual insp at meter	NO RECORD
226 S MCKAY AVENUE	N	c		/4"	C 1"			0	SL repair/replace record	N	Field inspection only	Y Visual insp at meter	r
226 W SOUTH THIRD STREET	N	С		/4"	C 3/4"			С	Installation record	N	Field inspection only	Y Visual insp at meter	r
227 N HERB AVENUE	N	С	N	1"	C 1"			C	SL repair/replace record	N	Field inspection only	Y Visual insp at meter	1
227 N MCKAY AVENUE 227 S NEWMAN AVENUE	N	C		/4" /4"	C 3/4"			C	Installation record Installed after lead ban	N N	Field inspection only Field inspection only	Y Visual insp at meter Y Visual insp at meter	
227 S NEWMAN AVENUE 227 W SOUTH THIRD STREET	N N	C	N 3	/4"	C 3/4"			0	Installed after lead ban Installation record	N	Field inspection only Field inspection only	Y Visual insp at meter Y Visual insp at meter	
228 S MCKAY AVENUE	N	C	N 3	/4"	C 1"			C	SL repair/replace record	N	Field inspection only	Y Visual insp at meter	
228 W CLEVELAND STREET	UNK	UNK-LG	UNK		C 3/4"			0	Other - describe in notes	N	Field inspection only	Y Visual insp at mete	NO RECORD
229 S NEWMAN AVENUE	N	С	N	1"	C 1"			0	Installation record	N	Field inspection only	Y Visual insp at meter	r
230 N HERB AVENUE 230 W FIRST STREET	N	C	N n	1" /4"	C 3/4"			C	SL repair/replace record	N N	Field inspection only Field inspection only	Y Visual insp at meter Y Visual insp at meter	
230 W FIRST STREET 231 N HERB AVENUE	N	C	N 3	1"	C 1"			C	Installation record SL repair/replace record	N	Field inspection only Field inspection only	Y Visual insp at meter Y Visual insp at meter	,
231 N MCKAY AVENUE	N	C	N 3	/4"	G 3/4"			0	Installation record	N	Field inspection only	Y Visual insp at meter	r
231 N NEWMAN AVENUE	N	С	N	1"	G 3/4"			C	Installation record	N	Field inspection only	Y Visual insp at meter	,
231 S BURRO LANE	N	С	N	1"	C 3/4"			0	Installed after lead ban	N	Field inspection only	Y Visual insp at meter	r
232 N MCKAY AVENUE 232 S MCKAY AVENUE	N N	C		/4" /4"	C 1"			C	Installation record SL repair/replace record	N N	Field inspection only Field inspection only	Y Visual insp at meter Y Visual insp at meter	
232 S MCKAY AVENUE 233 S CHURCH AVENUE	N N	C		/4"	C 3/4"			c	St repair/replace record Installed after lead ban	N	Field inspection only Field inspection only	Y Visual insp at meter Y Visual insp at meter	
 233 S MCKAY AVENUE	N	c		/4"	C 1/2"			0	SL repair/replace record	N	Field inspection only	Y Visual insp at meter Y Visual insp at meter	r
234 S GOLFVIEW DRIVE	N	С		/4"	C 3/4"			C	Installed after lead ban	N	Field inspection only	Y Visual insp at meter	r
234 S MCKAY AVENUE	N	С		/4"	C 1"			C	SL repair/replace record	N	Field inspection only	Y Visual insp at meter	1
235 N MCKAY AVENUE 236 N SABIN AVENUE	N N	C		/4"	G 3/4"			C	Installation record Installation record	N N	Field inspection only	Y Visual insp at meter	
236 N SABIN AVENUE 236 S BURRO LANE	N	C	N 3	/4" 1"	C 3/4"			C	Installation record Installed after lead ban	N N	Field inspection only Field inspection only	Y Visual insp at meter Y Visual insp at meter	
236 S MCKAY AVENUE	N	c	N 3	/4"	C 3/4"			C	SL repair/replace record	N .	Field inspection only	Y Visual insp at meter	r
237 N NEWMAN AVENUE	N	C	N	1"	C 3/4"			0	Installed after lead ban	N	Field inspection only	Y Visual insp at meter	r
237 S GOLFVIEW DRIVE	N	С		/4"	C 1"			C	Installation record	N	Field inspection only	Y Visual insp at meter	1
238 S CHURCH AVENUE 239 S CHURCH AVENUE	N N	C		/4" /4"	C 3/4"			C	Installation record Installation record	N N	Field inspection only Field inspection only	Y Visual insp at meter Y Visual insp at meter	
239 S GLADE AVENUE	UNK	UNK-LG	UNK	,-	C 1"			C	Other - describe in notes	N	Field inspection only Field inspection only	Y Visual insp at meter Y Visual insp at meter	
240 N NEWMAN AVENUE	N	C	N	1"	C 1 1/4	1"		0	Installation record	N	Field inspection only	Y Visual insp at meter	1
241 N MCKAY AVENUE	N	C	N 3	/4"	C 3/4"			C	Installation record	N	Field inspection only	Y Visual insp at meter	r
241 N NEWMAN AVENUE	N	С	N	1"	C 3/4"			0	Installation record	N	Field inspection only	Y Visual insp at meter	r
242 S MCKAY AVENUE	N N	C		/4"	C 1"			C	SL repair/replace record	N	Field inspection only	Y Visual insp at meter	
243 S MCKAY AVENUE 243 S MCKAY AVENUE	N N	C		/4" /4"	C 3/4"			0	SL repair/replace record SL repair/replace record	N N	Field inspection only Field inspection only	Y Visual insp at meter Y Visual insp at meter	
 		-			5/4				JE repuis repuide record		. ica mapecoon only	Vision map de meter	

25	555 W STATE ROAD 29	N C	N	1"	C	2"	C	Installed after lead ban	Field inspection only	Y Visual insp at meter	
	555 W STATE ROAD 29	N C	N	1"		1"	С	Installed after lead ban	Field inspection only	Y Visual insp at meter	
	01 W CENTRAL STREET 01 W NORTH 2ND STREET	N C	N N	3/4"		3/4"	C	SL repair/replace record Installation record	Field inspection only	Y Visual insp at meter	
	03 S CHURCH AVENUE	N C	N N	3/4"	C	3/4"	c	Installation record Installation I	Field inspection only	Y Visual insp at meter Y Visual insp at meter	
	03 S MCKAY AVENUE	N C	N N	3/4"	C	1"	C	SL repair/replace record N	Field inspection only Field inspection only	Y Visual insp at meter	
30	03 W NORTH 2ND STREET	UNK UNK-LG	UNK		C	3/4"	C	Other - describe in notes	Field inspection only	Y Visual insp at mete	NO RECORD
30	03 W STATE ROAD 29	N C	N	1"	c	3/4"	0	Installed after lead ban	Field inspection only	Y Visual insp at meter	
30	04 S MCKAY AVENUE	N C	N	3/4"		1"	C	Installed after lead ban	Field inspection only	Y Visual insp at meter	
30	04 W CENTRAL STREET	N C	N	3/4"	UNK-LG			SL repair/replace record 1	Other - describe in note:	N Other - describe in no un	unable to access hous
	04 W STATE ROAD 29	N C	N	1"		3/4"	C	Installed after lead ban	Field inspection only	Y Visual insp at meter	
30	05 W CENTRAL STREET	N C	N	3/4"	C	3/4"	C	SL repair/replace record	Field inspection only	Y Visual insp at meter	
30	06 S CHURCH AVENUE 06 W CLEVELAND STREET	UNK UNK-LG	UNK	3/4"	c	1"	C	Installation record  Other - describe in notes	Field inspection only Field inspection only	Y Visual insp at meter Y Visual insp at meter	NO RECORD
30	07 S GLADE AVENUE	UNK UNK-LG	UNK			1/2"	c	Other - describe in notes   Other - describe in notes	Field inspection only  Field inspection only	Y Visual insp at mete Y Visual insp at mete	NO RECORD
30	07 S SABIN AVENUE	N C		1 1/2"	C	1 1/2"	c	Installation record N	Field inspection only	Y Visual insp at meter	NO ILLCOID
	08 S SABIN AVENUE	N C	N N	3/4"	c	3/4"	c	Installation record 1	Field inspection only	Y Visual insp at meter	
	08 W NORTH 2ND STREET	N C	N	1"		1"	С	Installation record N	Field inspection only	Y Visual insp at meter	
30	09 E EAU GALLE ROAD	N C	N	1"	C	1"	С	Installed after lead ban	Field inspection only	Y Visual insp at meter	
30	09 W STATE ROAD 29	N C	N	1"		3/4"	C	Installed after lead ban	Field inspection only	Y Visual insp at meter	
31	10 E EAU GALLE ROAD	N C	N	1"		3/4"	C	Installed after lead ban	Field inspection only	Y Visual insp at meter	
	10 S BURRO LANE	N C	N	1"	C	3/4"	C	Installed after lead ban	Field inspection only	Y Visual insp at meter	
31	10 S SABIN AVENUE	N C	N	1"		1"	C	Installation record 1	Field inspection only	Y Visual insp at meter	
31	10 W STATE ROAD 29 11 W AKERS STREET	UNK UNK-LG	UNK	1"		3/4"	0	Installed after lead ban N	Field inspection only	Y Visual insp at meter Y Visual insp at mete	NO RECORD
31	11 W CENTRAL STREET	N C	N N	3/4"		1/2"	C	Other - describe in notes  St. repair/replace record	Field inspection only Field inspection only	Y Visual insplat meter	NO RECORD
	11 W CLEVELAND STREET	UNK UNK-LG	UNK			3/4"	C	Other - describe in notes	Field inspection only	Y Visual insp at mete	NO RECORD
31	12 S GLADE AVENUE	UNK UNK-LG	UNK			1/2"	0	Other - describe in notes	Field inspection only	Y Visual insp at mete	NO RECORD
	12 S MCKAY AVENUE	N C	N	1"	С	1"	C	Installation record 1	Field inspection only	Y Visual insp at meter	
	12 W CENTRAL STREET	N C	N	3/4"		3/4"	C	SL repair/replace record •	Field inspection only	Y Visual insp at meter	
31	13 E EAU GALLE ROAD	N C	N	1"		3/4"	0	Installed after lead ban	Field inspection only	Y Visual insp at meter	
	13 S GOLFVIEW DRIVE	N C	N C	3/4"		3/4"	C	Installed after lead ban	Field inspection only	Y Visual insp at meter	
31	14 N MCKAY AVENUE	N C	N .	3/4"	C	3/4"	C	Installed after lead ban Installed after lead ban Installed after lead ban	Field inspection only	Y Visual insp at meter	
	14 S NEWMAN AVENUE 14 W CLEVELAND STREET	N C	N	3/4"			0		Field inspection only	Y Visual insp at meter	
	15 E EAU GALLE ROAD	N C	N	1"		3/4"	C	Installed after lead ban Installed after lead	Field inspection only Field inspection only	Y Visual insp at meter Y Visual insp at meter	
	15 N SABIN AVENUE	N C	N	1"		3/4	c	Installed after lead ban Installed after lead	Field inspection only	Y Visual insp at meter Y Visual insp at meter	
31	15 S CHURCH AVENUE	N C	N	3/4"		3/4"	C	Installed after lead ban	Field inspection only	Y Visual insp at meter	
31	15 S GLADE AVENUE	UNK UNK-LG	UNK		C	3/4"	0	Other - describe in notes	Field inspection only	Y Visual insp at mete	NO RECORD
31	15 W CENTRAL STREET	N C	N	3/4"	UNK-LG			SL repair/replace record 1	Field inspection only	Y Visual insp at meter	
	15 W STATE ROAD 29	N C	N	1"			0	Installed after lead ban	I Field inspection only	Y Visual insp at meter	
31	16 E EAU GALLE ROAD	N C	N	1"		3/4"	0	Installed after lead ban	Field inspection only	Y Visual insp at meter	
31	16 S CHURCH AVENUE	N C	N	3/4"		3/4"	0	Installed after lead ban	Field inspection only	Y Visual insp at meter	
	16 W NORTH 2ND STREET 18 W NORTH 2ND STREET	N C	N	1"		1"	C	Installed after lead ban	Field inspection only	Y Visual insp at meter	
	18 W NORTH 2ND STREET	N C	N N	1"		1" 3/4"	0	Installed after lead ban Installed after lead ban	Field inspection only Field inspection only	Y Visual insp at meter Y Visual insp at meter	
	19 S GOLFVIEW DRIVE	N C	N N	3/4"		3/4	c	Installed after lead ban Installation record	Field inspection only	Y Visual insp at meter Y Visual insp at meter	
21	19 W CLEVELAND STREET	N C	N N	1"		3/4"	0	Installation record Installed after lead ban	Field inspection only Field inspection only	Y Visual insp at meter Y Visual insp at meter	
32	20 S MCKAY AVENUE	N C	N N	1"	c	1"	C	Installation record •	Field inspection only	Y Visual insp at meter	
32	20 S SABIN AVENUE	N C	N	3/4"	c	3/4"	0	Installation record N	Field inspection only	Y Visual insp at meter	
32	20 W CLEVELAND STREET	UNK UNK-LG	UNK		С	3/4"		Other - describe in notes	Field inspection only	Y Visual insp at mete	NO RECORD
32	22 W NORTH 2ND STREET	N C	N	1"	C	1"	C	Installed after lead ban	Field inspection only	Y Visual insp at meter	
32	23 E EAU GALLE ROAD	N C	N	1"		3/4"	С	Installed after lead ban	I Field inspection only	Y Visual insp at meter	
32	23 W STATE ROAD 29	N C	N	1"		3/4"	0	Installed after lead ban	Field inspection only	Y Visual insp at meter	
32	24 N MCKAY AVENUE	N C	N	3/4"		3/4"	0	Installation record I	Field inspection only	Y Visual insp at meter	
	24 W STATE ROAD 29	N C	N N	1"		3/4"	C	Installed after lead ban	Field inspection only	Y Visual insp at meter	
32	26 E EAU GALLE ROAD 26 W NORTH 2ND STREET	N C	N N	1"	C	3/4"	C	Installed after lead ban Installation record	Field inspection only Field inspection only	Y Visual insp at meter Y Visual insp at meter	
	27 N MCKAY AVENUE	N C	N N	3/4"	C	3/4"	0	Installation record N	Field inspection only	Y Visual insp at meter	
	27 N SABIN AVENUE	N C	N N	1"		3/4"	0	Installed after lead ban	Field inspection only	Y Visual insp at meter	
	29 E EAU GALLE ROAD	N C	N N	1"	c	1"	0	Installed after lead ban	Field inspection only	Y Visual insp at meter	
33	30 W NORTH 2ND STREET	N C	N	1"	C	1"	С	Installed after lead ban	Field inspection only	Y Visual insp at meter	
33	30 W OAK STREET	UNK UNK-LG	UNK		C	3/4"	C	Other - describe in notes	Field inspection only	Y Visual insp at mete	NO RECORD
	30 W STATE ROAD 29	N C	N	1"		3/4"	C	Installed after lead ban	Field inspection only	Y Visual insp at meter	
	31 W CLEVELAND STREET	N C	N	1"		1"	C	Installed after lead ban	Field inspection only	Y Visual insp at meter	
33	32 N MCKAY AVENUE	N C	N	1"	C	1"	0	Installed after lead ban	Field inspection only	Y Visual insp at meter	
33	32 W NORTH 2ND STREET 33 N SABIN AVENUE	N C	N N	1"	C	3/4"	C	Installed after lead ban Installed after lead	Field inspection only Field inspection only	Y Visual insp at meter Y Visual insp at meter	
	35 W CLEVELAND STREET	N C	N N	1"		3/4"	0	Installed after lead ban Installed after lead	Field inspection only  Field inspection only	Y Visual insp at meter Y Visual insp at meter	
22	35 W CLEVELAND STREET	UNK UNK-LG	LINK	1	C	1"	C	Other - describe in notes	Field inspection only	Y Visual insp at meter Y Visual insp at mete	NO RECORD
	36 E EAU GALLE ROAD	N C	N N	1"	C	3/4"	C	Installed after lead ban	Field inspection only	Y Visual insp at meter	NO ILECORD
33	36 N NEWMAN AVENUE	UNK UNK-LG	UNK			3/4"	С	Other - describe in notes	Field inspection only	Y Visual insp at mete	NO RECORD
33	38 W NORTH 2ND STREET	N C	N	1"	P	1*	C	Installed after lead ban	Field inspection only	Y Visual insp at meter	
33	39 N MCKAY AVENUE	N C	N	1"		1"	C	Installation record 1	Field inspection only	Y Visual insp at meter	
34	40 W NORTH 2ND STREET	N C	N	1"		1"	C	Installed after lead ban	Field inspection only	Y Visual insp at meter	
	40 W STATE ROAD 29	N C	N	1"		3/4"	C	Installed after lead ban	Field inspection only	Y Visual insp at meter	
	41 E EAU GALLE ROAD	N C UNK UNK-LG	N	1-		3/4"	C	Installed after lead ban	Field inspection only	Y Visual insp at meter	
34	41 W OAK STREET 42 N MCKAY AVENUE	N C	UNK	3/4"		1" 3/4"	0	Other - describe in notes	Field inspection only	Y Visual insp at meter Y Visual insp at meter	NO RECORD
34	42 N MCKAY AVENUE 43 N SABIN AVENUE	N C	N N	1"		3/4"	0	Installed after lead ban Installed after lead	Field inspection only Field inspection only	Y Visual insp at meter Y Visual insp at meter	
	44 E EAU GALLE ROAD	N C	N N	1"		1"	0	Installed after lead ban I	Field inspection only	Y Visual insp at meter	
34	44 N NEWMAN AVENUE	UNK UNK-LG	UNK			3/4"	C	Other - describe in notes	Field inspection only	Y Visual insp at mete	NO RECORD
	45 N MCKAY AVENUE	N C	N	3/4"	C	3/4"	0	Installed after lead ban	Field inspection only	Y Visual insp at meter	
	45 N NEWMAN AVENUE	N C	N	1"	C	1"	C	Installed after lead ban	Field inspection only	Y Visual insp at meter	
34	46 W NORTH 2ND STREET	N C	N	2*	C	1 1/2"		Installed after lead ban	Field inspection only	Y Visual insp at meter	
	49 N MCKAY AVENUE	N C	N	1"	C	1"	0	Installed after lead ban	Field inspection only	Y Visual insp at meter	
35	52 N MCKAY AVENUE 53 N SARIN AVENUE	N C	N N	3/4"	C	3/4"	0	Installed after lead ban	Field inspection only	Y Visual insp at meter Y 2022 Visual insp at meter	
	55 N MCKAY AVENUE	N C	N	3/4"			0	SL repair/replace record	Visual insp during install o SL repair/replace record	Y 2022 Visual insp at meter Y Visual insp at meter	
	01 S VAN BUREN ROAD	N C	N	1"	c	1"	c	Installation record Installed after lead ban	Field inspection only Field inspection only	Y Visual insp at meter Y Visual insp at meter	
	01 W NORTH 2ND STREET	N C	N N	3/4"	c	3/4"	c	Installation record 1	Field inspection only	Y Visual insp at meter	
40	02 S CHURCH AVENUE	N C	N	3/4"		3/4"	С	Installation record 1	Field inspection only	Y Visual insp at meter	
40	03 E PUMP STREET	N C	N	1"	C	3/4"	C	Installed after lead ban	Field inspection only	Y Visual insp at meter	
40	03 N FOOTE AVENUE	N C	N	1"	C	3/4"	C	Installation record N	Field inspection only	Y Visual insp at meter	
	04 E EAU GALLE ROAD	N C	N	1"			0	Installed after lead ban	Field inspection only Field inspection only	Y Visual insp at meter	
	05 S MCKAY AVENUE	N C	N	3/4"		3/4"	C	Installation record 1	Field inspection only	Y Visual insp at meter	
40	06 N DOUG BLEGEN DRIVE	N C	N	1"	P	1 1/2"	0	Installed after lead ban	Field inspection only	Y Visual insp at meter	
	06 S GLADE AVENUE	N UNK-NOLO	UNK	A**	C	3/4"	U	Other - describe in notes	Field inspection only	Y Visual insp at mete	NO RECORD
40	O7 S NEWMAN AVENUE	N UNK-NOLO	n N	1"	C	3/4"	c	Diameter > 2 inches	Field inspection only	Y Visual insp at meter Y Visual insp at meter	
	09 N MCKAY AVENUE	N C	N N	1"		1"	C	Installation record Installation In	Field inspection only	Y Visual insp at meter Y Visual insp at meter	
	09 S GLADE AVENUE	UNK UNK-LG	UNK			3/4"	С	Other - describe in notes	Field inspection only Field inspection only	Y Visual insp at meter	NO RECORD
	10 S CHURCH AVENUE	N C	N	1"	С	3/4"	С	Installation record I	Field inspection only	Y Visual insp at meter	
41	11 S VAN BUREN ROAD	N C	N	1"		1"	С	Installed after lead ban	Field inspection only	Y Visual insp at meter	
41	12 S MCKAY AVENUE	N C	N	1"	С	1*	0	Installed after lead ban	Field inspection only	Y Visual insp at meter	
41	13 S CHURCH AVENUE	N C	N	1"		3/4"	C	Installation record N	Field inspection only	Y Visual insp at meter	
	13 W NORTH 2ND STREET	N C	N	1"	C	3/4"	C	Installation record 1	Field inspection only	Y Visual insp at meter	
	13 W STATE ROAD 29	N C	N	1"	IP.	1"	C	Installed after lead ban	Field inspection only	Y Visual insp at meter	
41						a for					
41 41	13-417 N FOOTE AVENUE	N C	N	1"		3/4"	С	Installation record Installation In	Field inspection only Field inspection only	Y Visual insp at meter Y Visual insp at meter	

Company														
Company	416 E PUMP STREET	N	C	N	1"	C 3/4	4"		0	Installed after lead ban	N Field inspection only	Y	Visual insp at meter	
March 1997   1			C	N	1"				C			Y		NO RECORD
March   Marc			C C	N N	1"				0			Y		NO RECURD
Column		N	c	N	1"	C 3/4	4"		0		N Field inspection only	Y	Visual insp at meter	
Management	422 S MCKAY AVENUE	N	C	N	1"	C 1"			0		Y Field inspection only	Υ	Visual insp at meter	
Mathematical			UNK-LG	UNK	2/48				0	Other - describe in notes	N Field inspection only	Y	Visual insp at mete	NO RECORD
March   Marc			C						0			Y		
Column   C	425 W STATE ROAD 29	N	C	N	1"				c			Y		
March   Marc			С	N	1"	C 3/4	4"		C	Installation record	N Field inspection only	Υ	Visual insp at meter	
Mate	426 S CURTIS AVENUE		UNK-LG	UNK		C 3/4	4"		0	Other - describe in notes	N Field inspection only	Y	Visual insp at mete	NO RECORD
	427 E PUMP STREET		c	N .	1"	C 3/4	4"		C	Installed after lead ban	N Field inspection only	Y	Visual insp at meter	
			C			DI 4"	4"		C			Y		
Mile	437 N MCKAY AVENUE		C			C 3/4	4"				N Field inspection only	· Y		
March   Marc	443 W STATE ROAD 29	N	С	N	1"				0		N Field inspection only	Y	Visual insp at meter	
December	448 S VAN BUREN ROAD	N	С	N	1"	P 1"			0		N Field inspection only	ΥΥ		
No.   Company	501 S VAN BUREN ROAD		c	N N	1"	C 1"			C	Installed after lead ban	N Field inspection only	Y	Visual insp at meter	
			UNK-LG	UNK	2	C 3/4	4"		C			Y		NO RECORD
March   Marc	504 E BAHR STREET	UNK				C 3/4	4"		C	Other - describe in notes	N Field inspection only	Y		NO RECORD
March   Marc			С	N	1"	G 5/8	8"		С	Installation record	N Field inspection only	Y	Visual insp at meter	
March 1987   Mar			UNK-LG	UNK					C			Y		NO RECORD
March   Marc			C	N	1"	P 11	1/2"		O	Installed after lead ban	N Field inspection only	Y	Visual insp at meter	NO RECORD
Color   Colo			C		3/4"				C			4 Y		NO RECORD
Mile	507 S NEWMAN AVENUE	N	С	N	1"	C 3/4	4"		c			Y		
March 19	508 E EAU GALLE ROAD			N	1"	G 3/4	4"		С	Installed after lead ban	N Field inspection only	Y	Visual insp at meter	
Mile			UNK-LG		- 110	P 1"		****	0		N Field inspection only	Y		NO RECORD
March   Marc			C	N IINV	3/4"	P 1	4"	2023	0	Field inspection only Other describe in poten	Y Visual insp during install o Field inspection only	Y	Visual insp during install or rep	NO RECORD
Company			C		3/4"				ō			Y	Visual insp at meter	NO NECOND
Part	510 S HIDDEN FOX COURT	N	С	N	1"	C 11	1/2"		0		N Field inspection only	Y	Visual insp at meter	
Discription		UNK	UNK-LG	UNK					C	Other - describe in notes	N Field inspection only	Y	Visual insp at mete	NO RECORD
Column   C		N N	C	N	1"				C	Installation record	N Field inspection only	Y		
Margare   Marg	514 N RIVERVIEW DRIVE 514 S NEWMAN AVENUE		C	N N	1"	C 2/4	4"		C	Installed after lead ban	N Field inspection only N Field inspection only	Y		
March Anthon Mar	 514 W OAK STREET		C	N	1"	C 3/4	4"		C	Other - describe in notes	N Field inspection only	Y	Visual insp at mete	NO RECORD
Description	515 N MCKAY AVENUE	N	С		3/4"	C 3/4	4"		0	Other - describe in notes	N Field inspection only	Y	Visual insp at mete	NO RECORD
March   Marc	515 S CURTIS AVENUE								0	Other - describe in notes	N Field inspection only	Y	Visual insp at mete	NO RECORD
Company of the Comp	516 S CURTIS AVENUE		UNK-LG	UNK					C	Other - describe in notes		Y		NO RECORD
Mail Company   Mail	518 N MCKAY AVENUE	N N	C	N N	1"	C 3/4	4"		0		N Field inspection only N Field inspection only	Y Y	Visual insp at meter	
Maintainment   Main		N	c	N	1"				C			Y		
Maintaine	519 S NEWMAN AVENUE	N	С	N	1"	C 3/4	4"		C	Installation record	N Field inspection only	Y	Visual insp at meter	
Section   March   Ma		N	С	N	1"				C		N Field inspection only	Υ	Visual insp at meter	
Marie   Mari		N	C	N	1"				C			Y		NO DECOMP
Part	524 S NEWMAN AVENUE		C C	UNK N	1"	C 3/4	4"		0	Installation record	N Field inspection only N Field inspection only	Y		NO RECORD
The Contract Contra	525 N FOOTE AVENUE		UNK-LG	UNK	-	C 1"			0	Other - describe in notes	N Field inspection only	Y	Visual insp at mete	NO RECORD
Top You Man Conf.   1	525 S CURTIS AVENUE		UNK-LG						C	Other - describe in notes	N Field inspection only	Y	Visual insp at mete	NO RECORD
Statistical Control	528 W GOLFVIEW DRIVE	N	С	N	1"	C 3/4	4"		C	Installed after lead ban	N Field inspection only	Y		
March   Marc	528 W PARK DRIVE	N N	C	N N	2"	C 2"	4"		C			Y		
STATE   Control of Annual   Control of Annua	534 N RIVERVIEW DRIVE		C			P 1"	+		C	Installed after lead han	N Field inspection only	Y	Visual insp at meter	
Call Interference Amen	537 N FOOTE AVENUE	UNK	UNK-LG		-	C 1"			C	Other - describe in notes		Y	Visual insp at mete	NO RECORD
Sep 1976 (1902)   Sep 1	542 N RIVERVIEW DRIVE		С		1"	C 1"			C			Υ	Visual insp at meter	
March   Marc		UNK	UNK-LG	UNK					C			Y		NO RECORD
Contract		N N	C	N N	1"				C			Y	Visual insp at meter	
March   Marc	600 W GOLFVIEW DRIVE		C	N	1"				C	Installation record	N Field inspection only	Y	Visual insp at meter	
COLVESTINGE   No.   C.   N.   1º   C.   No.	602 S BUCKLEY COURT	N	c	N 1	1/2"					Installed after lead ban	N Field inspection only	Y	Visual insp at meter	
GON NOTIFICATION.  (A) MARIE MONEY DE MANAGE MAN COMMINISTER MAN COMMINISTER MANAGE MAN COMMINISTER MAN COMMINISTER MANAGE MAN COMMINISTER MAN COMMIN		N	С	N	1"				C		N Field inspection only	Y	Visual insp at meter	
Company   Comp			C	N	1"				C			Y		
11 SECRET   N			UNK-LG	UNK	1"				C			Y		NO RECORD
Company   Comp	611 S BUCKLEY	N	c	N N	1"	P 1"	•	2022	0		Y Visual insp during install o Installed after lead bar	Y	Visual insp during install or rep	pair
627 # I COST AND MANUAL PROPERTY CONT.   14	612 S BUCKLEY		С	N	1"	P 1"		2022	0	Installed after lead ban	Y Visual insp during install o Installed after lead bar	Υ	Visual insp during install or rep	pair
637 W (GATE NO )   7									0	Other - describe in notes	N Field inspection only	ΥΥ	Visual insp at mete	NO RECORD
GSSS WATER READORS		UNK	UNK-LG	UNK	1"				C		N Field inspection only	Y		NO RECORD
C31 NUCLEI COUNTY   N		N	C	N N	1"				C			, ,	Visual insp at meter	
C23 SEACKIT COUNTY	621 S BUCKLEY COURT	N	c	N	1"	P 11	1/2"		0	Installed after lead ban	N Field inspection only	Y	Visual insp at meter	
CAS PROFILE AND SET   Was 1	622 S BUCKLEY COURT		С	N	1"	C 11	1/2"		0	Installed after lead ban	N Field inspection only	Y	Visual insp at meter	
C39 Work) 246   N	625 N FOOTE AVENUE		UNK-LG	UNK	41	G 3/4	4"		C	Other - describe in notes	N Field inspection only	Y	Visual insp at mete	NO RECORD
GDE MARK-YMM DRIVE   N   C   N   M/4"   C   M/4"   M/4"   C   M/		N N	C	N	1"			2020	C			Y		
GRM OCCUPYIND MOVE   N   C   N   1"   C   1"   C   Installation record   N   Fled Impaction only   Y   Visual ing at meter	630 E MARY-LYNN DRIVE	N	C	N	3/4"			2,020	c	Installed arter lead ban Installation record		Y	visual insp at meter Visual insp at meter	
GeV N M CHY 2	634 W GOLFVIEW DRIVE	N	С	N	1"	C 1"			C		N Field inspection only	Y	Visual insp at meter	
Column   C	638 E MARY-LYNN DRIVE	N	С			C 3/4	4"		C		N Field inspection only	Y	Visual insp at meter	
Top   Foundation   Top   Field   Top   Fie		N	P	N N	1/2"	C 1"	4"	2021	0		Y Visual insp during install o Field inspection only	Y	Visual insp at meter	
Page		N N	C						C		N Field inspection only	Y	Visual insp at meter Visual insp at meter	
Table MARK-YNN DRIVE   N		N	c	N	1"				C			Y	Visual insp at meter	
726 MANF-LYNN DRIVE   N   C   N   3/4"   C   3/4"   C   1/4"   C   Installation record N   Field inspection only V   Visual insp at meter   746 W GOLVIPW DRIVE N   C   N   1"   P   1 1/2"   O   Installed after lead ban N   Field inspection only V   Visual insp at meter   766 W GOLVIPW DRIVE N   C   N   1"   P   1 1/2"   O   Installed after lead ban N   Field inspection only V   Visual insp at meter   768 W GOLVIPW DRIVE N   C   N   1"   P   1 1/2"   O   Installed after lead ban N   Visual insp during install or repair   Visual insp at meter   781 W SILVER FOX DRIVE N   C   N   1"   2024   D   1"   2024   O   Installed after lead ban N   Visual insp during install or repair   Visual insp during install or repa	718 E MARY-LYNN DRIVE		С			C 3/4	4"		C	Installation record	N Field inspection only	Y	Visual insp at meter	
The control of the	724 W GOLFVIEW DRIVE	N	С			C 3/4	4"		C	Installed after lead ban	N Field inspection only	Y	Visual insp at meter	
To No SULVER FOX DRIVE   N		N N	C			C 3/4	4-		C		N Field inspection only	Y	Visual insp at meter	
76 W GOLPVIEW DRIVE   N			C	N N	1"				0			Y		
781 W SILVER FOX DRIVE	766 W GOLFVIEW DRIVE	N	C	N	1"	C 1"			С	Installed after lead ban	N Field inspection only	Y	Visual insp at meter	
SOW_SHURE FOX DRIVE   N   C   N   1"   P   1"   C   Installed after lend ban   N   Field inspection only   V   Visual insp. at meter	781 W SILVER FOX DRIVE		С	N	1" 2024	P 1"		2024	0	Installed after lead ban	Y Visual insp during install o Installed after lead bar	Υ	Visual insp during install or rep	pair
ADJ WALVER FOX DRIVE   N	788 W EVERGREEN COURT		С	N	1"	C 1"			C	Installed after lead ban	N Field inspection only	Y	Visual insp at meter	
20.5 WESTLAND DRIVE			C	N N	1"	P 1"	1/2"		0			Y	Visual insp at meter	
200 SWESTLAND DRIVE   N   C   N   1"   C   1"   C   Installed after lead ban N   Field inspection only V   Visual insp. at meter   200 SWESTLAND DRIVE   N   C   N   1"   P   112"   O   Installed after lead ban N   Field inspection only V   Visual insp. at meter   200 SWESTLAND DRIVE   N   C   N   1"   P   112"   O   Installed after lead ban N   Field inspection only V   Visual insp. at meter   21 SWESTLAND DRIVE   N   C   N   1"   C   112"   O   Installed after lead ban N   Field inspection only V   Visual insp. at meter   23 SWESTLAND DRIVE   N   C   N   1"   C   1/4"   C   Installed after lead ban N   Field inspection only V   Visual insp. at meter   23 SWESTLAND DRIVE   N   C   N   1"   C   1/4"   C   Installed after lead ban N   Field inspection only V   Visual insp. at meter   24 SWESTLAND DRIVE   N   C   N   1"   C   3"   C   Installed after lead ban N   Field inspection only V   Visual insp. at meter   24 SWESTLAND DRIVE   N   C   N   1"   C   3"   C   Installed after lead ban N   Field inspection only V   Visual insp. at meter   24 SWESTLAND DRIVE   N   C   N   1"   C   3"   C   Installed after lead ban N   Field inspection only V   Visual insp. at meter   24 SWESTLAND DRIVE   N   C   N   1"   P   1"   C   Installed after lead ban N   Field inspection only V   Visual insp. at meter   24 SWESTLAND DRIVE   N   C   N   1"   P   1"   C   Installed after lead ban N   Field inspection only V   Visual insp. at meter   24 SWESTLAND DRIVE   N   C   N   1"   P   1"   C   Installed after lead ban N   Field inspection only V   Visual insp. at meter   24 SWESTLAND DRIVE   N   C   N   1"   P   1"   C   Installed after lead ban N   Field inspection only V   Visual insp. at meter   24 SWESTLAND DRIVE   N   C   N   1"   P   1"   C   Installed after lead ban N   Field inspection only V   Visual insp. at meter   24 SWESTLAND DRIVE   N   C   N   1"   P   1"   C   Installed after lead ban N   Field inspection only V   Visual insp. at meter   24 SWESTLAND DRIVE   N   C   N   1"   P   1"   C   N   1"   N   1"   N   1"   N			C	N	1"				c	Installed after lead ban	N Field inspection only	Y		
SAD WSLVER FOX DRIVE N C N 1 1 P 1 1 1 2 O   Installed after lead ban N   Field inspection only V   Visual rings at meter		N	C	N	1"	C 1"			С	Installed after lead ban		Y		
S21 W SILVER FOX DRIVE   N   C   N   1"   C   1.1/2"   O   Installed after lend ban   N   Field inspection only   V   Visual insp. at meter	820 W SILVER FOX DRIVE		С	N	1"				0	Installed after lead ban	N Field inspection only	Y	Visual insp at meter	
22 W VVERGRESH COURT   N	820 W SILVER FOX DRIVE		c	N	1"				0	Installed after lead ban	N Field inspection only	Y	Visual insp at meter	
830 SWESTLAND DRIVE N C N 1° C 1° C Installed after lead ban N Field inspection only Y Visual inspat meter 830 SWESTLAND DRIVE N C N 1° C 3° C Installed after lead ban N Field inspection only Y Visual inspat meter 840 W SULVER FOX DRIVE N C N 1° P 1° O Installed after lead ban N Field inspection only Y Visual inspat meter 841 W SULVER FOX DRIVE N C N 1° P 1° C Installed after lead ban N Field inspection only Y Visual inspat meter 843 W SULVER FOX DRIVE N C N 1° P 1° C Installed after lead ban N Field inspection only Y Visual inspat meter 844 W SULVER FOX DRIVE N C N 1° P 1° C Installed after lead ban N Field inspection only Y Visual inspat meter			C	N N	1"				C		N Field inspection only	Y Y	Visual insp at meter	
830 SWESTLAND DRIVE   N C N 1			C	N	1"	C 1"			C	Installed after lead ban	N Field inspection only	Y		
SAUW SULVER FOX DRIVE   N C N 1"   P 1"   O Installed after lead ban N Field inspection only Y Visual insp. at meter	830 S WESTLAND DRIVE	N	C	N	1"	C 3"			C	Installed after lead ban	N Field inspection only	Υ	Visual insp at meter	
860 W SILVER FOX DRIVE N C N 1" P 1" O Installed after lead ban N Field inspection only Y Visual insp at meter	840 W SILVER FOX DRIVE	N	С	N	1"	P 1"			0	Installed after lead ban	N Field inspection only	Y	Visual insp at meter	
	841 W SILVER FOX DRIVE	N	C	N	1"	P 1"			C	Installed after lead ban	N Field inspection only	Y	Visual insp at meter	
	860 W SILVER FOX DRIVE 861 W SILVER FOX DRIVE	N N	C	N N	1"	P 1"			C	Installed after lead ban Installed after lead ban	N Field inspection only N Field inspection only	Y	Visual insp at meter Visual insp at meter	
Bot W SAVER FUX LINIVE N C N 1 C 1 C Installed after lead ban N Field impection only Y Visual ring at meter S SS W EVERSER FUCHS T N C N 12* C 2* C Installed after lead ban N Field impection only Y Visual ring at meter			C	N	1"	C 1"			c			Y		
868 W EVERGREEN COURT N C N 1" P 1" C Installed after lead ban N Field inspection only Y Visual insp at meter	868 W EVERGREEN COURT	N	С	N	1"	P 1"			C	Installed after lead ban	N Field inspection only	Υ	Visual insp at meter	
875 W EVERGREEN COURT N C N 1° C 1° C Installed after lead ban N Field inspection only Y Visual insp at meter	875 W EVERGREEN COURT	N	С	N	1"	C 1"			c		N Field inspection only	Υ		

8	180 W SILVER FOX DRIVE	N	C	N	1"	P	1"	2022	0	Installed after lead ban	Y	Visual insp during install o Installed after lead ban	Υ	Visual insp during install or repair
8	181 W SILVER FOX DRIVE	N	C	N	1"	C	1"		C	Installed after lead ban	N	Field inspection only	Y	Visual insp at meter
8	88 W EVERGREEN COURT	N	С	N	1"	C	1"		C	Installed after lead ban	N	Field inspection only	Υ	Visual insp at meter
9	100 S WESTLAND DRIVE	N	C	N	1"	P	3/4"		0	Installed after lead ban	N	Field inspection only	Y	Visual insp at meter
9	100 W CARDINAL DRIVE	N	C	N	1"	c	1"		C	Installed after lead ban	N	Field inspection only	Υ	Visual insp at meter
9	100 W SILVER FOX DRIVE	N	C	N	1"	C	1 1/2"		0	Installed after lead ban	N	Field inspection only	Y	Visual insp at meter
9	IOS S BELTLINE ROAD	N	C	N	1"	C	1"		C	Installed after lead ban	N	Field inspection only	Υ	Visual insp at meter
9	109 S BELTLINE ROAD	N	С	N	1"	C	1"		c	Installed after lead ban	N	Field inspection only	Y	Visual insp at meter
9	10 S BELTLINE ROAD	N	С	N	1"	P	1"		0	Installed after lead ban	N	Field inspection only	Υ	Visual insp at meter
9.	20 W CARDINAL DRIVE	N	C	N	1"	C	1"		C	Installed after lead ban	N	Field inspection only	Y	Visual insp at meter
9.	20 W SILVER FOX DRIVE	N	C	N	1"	P	1 1/2"		0	Installed after lead ban	N	Field inspection only	Y	Visual insp at meter
9.	21 W SILVER FOX DRIVE	N	C	N	1"	C	1"		0	Installed after lead ban	N	Field inspection only	Y	Visual insp at meter
9.	40 W CARDINAL DRIVE	N	С	N	1"	C	1"		C	Installed after lead ban	N	Field inspection only	Y	Visual insp at meter
9	140 W SILVER FOX DRIVE	N	C	N	1"	C	1 1/2"		0	Installed after lead ban	N	Field inspection only	Y	Visual insp at meter
9.	141 W SILVER FOX DRIVE	N	C	N	1"	P	1"		C	Installed after lead ban	N	Field inspection only	Y	Visual insp at meter
9	60 W CARDINAL DRIVE	N	С	N	1"	C	1"		c	Installed after lead ban	N	Field inspection only	Y	Visual insp at meter
9	60 W SILVER FOX DRIVE	N	C	N	1"	P	1"		c	Installed after lead ban	N	Field inspection only	Y	Visual insp at meter
9	60 W SILVER FOX DRIVE	N	c	N	1"	P	1"		0	Installed after lead ban	N	Field inspection only	Y	Visual insp at meter
9	61 W SILVER FOX DRIVE	N	C	N	1"	C	1 1/2"		0	Installed after lead ban	N	Field inspection only	Y	Visual insp at meter
9	72 W RED FOX RUN	N	C	N	1"	P	1"	2021	0	Installed after lead ban	N	Field inspection only	Y	Visual insp at meter
9	75 W RED FOX RUN	N	C	N	1"	Р	1"	2022	0	Installed after lead ban	Y	Visual insp during install o Installed after lead ban	Y	Visual insp during install or repair
9.	80 W SILVER FOX DRIVE	N	C	N	1"	Р	1"		0	Installed after lead ban	N	Field inspection only	Y	Visual insp at meter
	182 W RED FOX RUN	N	c	N	1"	P	1"	2022	0	Installed after lead ban	Y	Visual insp during install o Installed after lead ban	Y	Visual insp during install or repair
	185 W RED FOX RUN	N	c	N	1"	P	1"	2024	0	Installed after lead ban	Y	Visual insp during install o Installed after lead ban	Y	Visual insp during install or repair
	192 W RED FOX RUN	N	C	N	1"	P	1"	2022	0	Installed after lead ban	Y	Visual insp during install o Installed after lead ban	Υ	Visual insp during install or repair
	199 W RED FOX RUN	N	C	N	1"	P	1 1/2"	2021	0	Installed after lead ban	N	Field inspection only	Y	Visual insp at meter